



REIDS PLAYGROUND MAINTENANCE LTD

Registered Office: Cabot House, 108 Gipsy Lane, Kettering, Northamptonshire, NN16 8UB.

Telephone: 01536 601950

Email: rpm@reidsplayground.co.uk **Website:** www.reidsplaygroundmaintenance.co.uk

QUOTE RPM/10479

Following the RoSPA inspection report, the contractor quoted £4,705+vat for all the items mentioned, but MPC had only budgeted £2,000 having spent £5,455+vat last year on a number of similar repairs. The report has no repairs flagged red for immediate response, most are green/low risk, a couple are amber/medium risk. Cllr Phillips and I have now inspected the play equipment against the list of quoted repairs - full report attached. The recommendation is that only two repairs are actioned, stripping down and refitting the HipHop and Rotaweb at £285.00 each +vat - although both of these were done last year. In addition, I have contacted the local jet wash company, who kindly cleaned off the graffiti on the slide, for a quote to clean moss and algae off the Toddler MultiUnit and the Slide Tower - and anything else he's willing to do. For the ongoing issues with the wet pour shrinkage, we suggest trying a repair kit at around £60+vat. For all other repairs the recommendation is to leave them until next year's inspection, which gives MPC the chance to carry forward any funding from this year's budget and properly budget for 2027-2028 to cover up to £5,000 in repairs - there is also the suggestion of looking to replace the wet pour surfaces with the same as that under the Slide Tower which is less prone to shrinkage and cracking.

Ref: Maulden Recreation Ground	Cost
Sign RPM to remove excess metal on the sign Low 5 David mended	£ 40.00
Senior Unit RPM to strip down pole spinner, lubricate and check parts for wear Med 8 Please note if parts are worn we will need to quote Leave till next year (done last year at £185+vat)	£185.00
RPM to supply and spread soil and seed to eliminate trip hazard Low 6 Leave till next year (done last year at £60+vat)	£130.00
Slide Tower RPM to sand down the deck where required to remove burns and algae Low 6 Ask local chap to jetwash algae	£140.00
RPM to supply and spread soil and seed to eliminate trip hazard Low 6 Leave till next year (done last year inc cleaning at £150+vat)	£130.00
2 Bay 4 Flat Seat Swing RPM to strip down the above item, check parts for wear, lubricate and re-fit item Please note if parts are worn we will need to quote Med 4 leave till next year (done last year at £300+vat)	£285.00
RPM to re-secure loose fixings on the seats Low 6 David done	£120.00
RPM to cut out 1 l/m of wet pour shrinkage and relay with new black rubber Low 4 Leave till next year/use wetpour repair kit (done last year at £510+vat)	
Bird Rocker RPM to smooth off rough edges. Low 6 leave (done last year at £40+vat)	£ 60.00
Toddler Multiunit RPM to jet wash the surface on the above item to remove moss and algae Med 9 Ask local chap to jetwash algae (done last year at £180+vat)	£600.00
RPM to rub down, prime and paint 1 No. handle using red colour lead free paint Low leave till next year	£185.00
Igloo	

Specialists in, Maintenance, Installation, On Site Welding and Fabricating

Company Registration No: 6249254

VAT No: 924 9588 76



REIDS PLAYGROUND MAINTENANCE LTD

Registered Office: Cabot House, 108 Gipsy Lane, Kettering, Northamptonshire, NN16 8UB.

Telephone: 01536 601950

Email: rpm@reidsplayground.co.uk **Website:** www.reidsplaygroundmaintenance.co.uk

QUOTE RPM/10479

RPM to cut out 2 No areas of cracked wet pour and relay with new black rubber Low 4 Leave till next year/use wetpour repair kit (done last year at £100+vat)	£260.00
Rocking Horse	
RPM to sand down footrest edges and stain with a preservative Low 6	£100.00
RPM to touch up red paint where required Low 2 Leave till next year (done last year at £85+vat)	£100.00
Hip Hop	
RPM to strip down the above item, check mechanism for wear, secure loose fixings and re-fit item Med 8 – RPM to action (done last year at £300+vat)	£285.00
Please note if parts are worn we will need to quote	
RPM to cut out 10 l/m of wet pour shrinkage and relay with new black rubber Med 4 fill with wetpour repair kit (Done last year at £850+vat)	£850.00
Rota Web	
RPM to strip down the above item, check mechanism for wear and re-fit item	£285.00
Please note if parts are worn we will need to quote Med 8 – RPM to action (done last year at £220+vat)	
Pod Swing	
RPM to re-position rubber bumpers on the seat as best we can Med 0 Leave (done last year at £30+vat)	£ 60.00
RPM to smooth off rough edge on the blue seat Med 8 Leave (done last year at £40+vat)	£ 40.00
Rodeo Board	£850.00
RPM to cut out 10 l/m of wet pour shrinkage and relay with new black rubber Low 6 fill with wetpour repair kit (done last year at £850+vat)	
Quotes issued will be valid for a period of 3 weeks only due to rising cost in materials	
All prices quoted are subject to VAT	£4705+vat

£570+vat

Plus wetpour repair kit
Black kit £34.50+vat
Base kit £24.00+vat